

WEEKLY EROSION CONTROL INSPECTION

PROJECT:	Avalon Bay Stratford, CT	DATE:	November 27, 2013
CONTRACTOR:	AMEC	PROJECT NO.:	86 16038
PREPARED BY:	Ken Kohlbrenner, PE	REPORT NO.:	17
SIGNATURE:	Ty the	PERMIT NO.:	IWWA #2001-9(M)

1. Initial Remarks/Comments:

Heavy rain (1.4") overnight. Rain expected to continue throughout the day. No sediment discharge evident. Some minor ponding and erosion channels onsite. Minimal work today due to rain.

2. Weather and Site Conditions:

Time	Precipitation	Skies	Air Temp	Ground/Pavement Moisture
7:00 AM	Rain	Cloudy	61°	Wet

3.	Did observation	ns reveal work <i>not</i> in compliance with the Erosion Control Plan?
	☐ Yes	⊠ No
	If yes, explain ar	nd describe action taken.
4.	Are the erosion in run-off from	and sediment control measures in place adequately installed to capture sediment the site?
	⊠ Yes □	1 No

Comment: NA



WEEKLY EROSION CONTROL INSPECTION

5.	Walk around the site perimeter to identify areas where sediment may escape from the site. Do areas to be disturbed drain to an area where sediment will be captured by silt fencing, hay bales, catch basins or equal measure?		
	Comment. NA		
6.	Are previously disturbed areas in need of hydro-seeding or manual seeding?		
	□ Yes 区 No		
	Comment: NA		
7.	Do disturbed areas drain to a drainage swale, sediment basin or protected stormwater systems?		
	☑ Yes ☐ No		
	Comment: NA		
8.	Are the construction vehicle entrances/exits free of sediment, mud or trash?		
	☑ Yes □ No		
	Comment: NA		
9.	Are erosion channels visible in the project area?		
	☑ Yes ☐ No		
	Comment: Minor erosion channels (see photos)		



WEEKLY EROSION CONTROL INSPECTION

10.	Is dust control water spraying required?			
	□ Yes	⊠ No		
	Occurring as	required?	⊠ Yes	□ No
	Comment: N	A		
11.	Are there dis	turbed are	as that could	cause ponding of run-off, other than a sediment basin?
	□ Yes	⊠ No		
	Comment: N	A		
12.	Are the silt fe	ences insta	alled as show	n on the Erosion and Sediment Control Drawing?
	⊠ Yes	□ No		
	Comment: N	A		
13.	Additional Co	omments/A	Areas of Conc	ern:
	Photos of dete	ention basir	n and construc	tion entrance at Circle Drive.

Photographs to be Attached to Form as Needed







