

WEEKLY EROSION CONTROL INSPECTION

PROJECT:	Avalon Bay Stratford, CT	DATE:	March 6, 2014
CONTRACTOR:	AMEC	PROJECT NO.:	86 16038
PREPARED BY:	Ken Kohlbrenner, PE	REPORT NO.:	25
SIGNATURE:	Ty the	PERMIT NO.:	IWWA #2001-9(M)

1. Initial Remarks/Comments:

Continued cold temperatures are reducing dust and sediment tracked offsite. Areas of silt fence will need to repaired when warmer weather allows (examples noted in pictures).

2. Weather and Site Conditions:

Time	Precipitation	Skies	Air Temp	Ground/Pavement Moisture
4:00 PM	None	Clear	28°	Frozen

3.	Did observations reveal work <i>not</i> in compliance with the Erosion Control Plan?		
	□ Yes	⊠ No	
	If yes, explain and NA	d describe action taken.	

4. Are the erosion and sediment control measures in place adequately installed to capture sediment in run-off from the site?

☐ Yes ⊠ No

Comment: Some areas of silt fence/hay bales need repair.



WEEKLY EROSION CONTROL INSPECTION

5.	Walk around the site perimeter to identify areas where sediment may escape from the site. Do areas to be disturbed drain to an area where sediment will be captured by silt fencing, hay bales, catch basins or equal measure?		
		□ No	
	Comment: N.	A	
6.	Are previous	sly disturbed areas in need of hydro-seeding or manual seeding?	
	□ Yes	⊠ No	
	Comment: N.	A	
7.	Do disturbed	d areas drain to a drainage swale, sediment basin or protected stormwater systems?	
	⊠ Yes	□ No	
	Comment: NA	4	
8.	Are the cons	struction vehicle entrances/exits free of sediment, mud or trash?	
	⊠ Yes	□ No	
	Comment: N.	A	
9.	Are erosion	channels visible in the project area?	
	⊠ Yes	□No	
	Comment: M	linor erosion channels in detention basin	



WEEKLY EROSION CONTROL INSPECTION

10.	Is dust control water spraying required?
	□ Yes ⊠ No
	Occurring as required? ✓ Yes ✓ No
	Comment: NA
11.	Are there disturbed areas that could cause ponding of run-off, other than a sediment basin?
• • •	
	□ Yes ⊠ No
	Comment: NA
12.	Are the silt fences installed as shown on the Erosion and Sediment Control Drawing?
	⊠ Yes □ No
	Comment: NA
13.	Additional Comments/Areas of Concern:
	Photos of areas where silt fence repair needed. 1. South of Building 4 2. South of Building 3 3. South of Building 1

Photographs to be Attached to Form as Needed





