

WEEKLY EROSION CONTROL INSPECTION

PROJECT:	Avalon Bay Stratford, CT	DATE:	July 28, 2014
CONTRACTOR:	AMEC	PROJECT NO.:	86 16038
PREPARED BY:	Ken Kohlbrenner, PE	REPORT NO.:	39
SIGNATURE:	By the	PERMIT NO.:	IWWA #2001-9(M)

1	Initial	Romarke	/Comments

Pervious concrete pavers complete near Building 3. Pervious concrete paver installation near Building 5 underway. Trench drain installed across driveway near Circle Drive.

0.16" rainfall overnight. No erosion evident.

2. Weather and Site Conditions:

Time	Precipitation	Skies	Air Temp	Ground/Pavement Moisture
11:00 AM	None	Mostly Cloudy	77°	Damp

3. Did observations reveal work <i>not</i> in compliance with the Erosion C	
	Control Dion?
3. Did observations reveal work <i>not</i> in combinance with the crosion c	Control Plan ?

☐ Yes

⊠ No

If yes, explain and describe action taken.

4. Are the erosion and sediment control measures in place adequately installed to capture sediment in run-off from the site?

□ No

Comment: NA



WEEKLY EROSION CONTROL INSPECTION

5.	Walk around the site perimeter to identify areas where sediment may escape from the site. Do areas to be disturbed drain to an area where sediment will be captured by silt fencing, hay bales, catch basins or equal measure?	
		□ No
	Comment: NA	
6.	Are previously	y disturbed areas in need of hydro-seeding or manual seeding?
	□ Yes	⊠ No
	Comment: NA	
7.	Do disturbed a	areas drain to a drainage swale, sediment basin or protected stormwater systems?
		□ No
	Comment: NA	
8.	Are the constr	ruction vehicle entrances/exits free of sediment, mud or trash?
	⊠ Yes	□ No
	Comment: NA	
9.	Are erosion cl	hannels visible in the project area?
	□ Yes	⊠ No
	Comment: NA	



WEEKLY EROSION CONTROL INSPECTION

10.	Is dust control water spraying required?
	⊠ Yes □ No
	Occurring as required? ☐ Yes ☐ No
	Comment: NA
11.	Are there disturbed areas that could cause ponding of run-off, other than a sediment basin?
	□ Yes 区 No
	Comment: NA
12.	Are the silt fences installed as shown on the Erosion and Sediment Control Drawing?
	⊠ Yes □ No
	Comment: NA
13.	Additional Comments/Areas of Concern:
	Photos of trench drain near Circle Drive.

Photographs to be Attached to Form as Needed



